Sl. No.	Name of Monuments	2004-05
46.	Fort at Vattakottaki 16th Century AD at Vattakottai, Distt. Kanyakumari	8,32,000/-
47.	Sri Bhagavati Temple and Jaina-Bas-Reliefs at Chitrai, Distt. Kanyakumari	1,60,000/-
48.	Sri Parthasarathy and Krishna Temple, Parthivapuram, Distt. Kanyakumari	3,53,000/-
49.	Rock cut Cave, Thirunandikkare, Distt. Kanyakumari	50,000/-
50.	Bhakhtavatsala Temple at Cheranmahadevi Distt. Thirunelveli	10,20,000/-
51.	Veleeswara Temple at Thiruvaleeswaram Distt. Thiruneeveli	8,58,000/-
52.	Ancient site at Kunathur	1,44,000/-
	TOTAL	5,13,93,311/-

Water seepage in Sanchi Stupa

†1958. SHRI MOTILAL VORA:
SHRIMATI PREMA CARIAPPA:

Will the Minister of CULTURE be pleased to state:

(a) whether Government are aware that 'Sanchi Stupa', included in the world heritage list, has developed cracks and water is seeping from many places;

(b) if so, the date since when water has been seeping from the 'Stupa' as well as when Government have noticed it;

(c) whether it is a fact that existence of 'Stupa' is in danger as a result of continuous water seepage; and

(d) if so, the steps taken by Government to save the 'Sanchi Stupa'?

THE MINISTER OF CULTURE (SHRI S. JAIPAL REDDY): (a) to (d) No cracks have developed in the Stupa at Sanchi.

During the conservation works undertaken at the Stupa by Sir John Marshall between 1912-1919, weep holes were provided for draining out the percolated rain water. Seepage through the weep holes is a normal process and is a prerequisite to save the structure from damage.

There is no damage to the Stupa. Conservation works such as pointing between the joints of stones, casing and water tightening measures are undertaken, where ever required.

†Original notice of the question was received in Hindi.